GUERARD, KALINA & BUTKUS

ATTORNEYS AT LAW

RICHARD M. GUERARD MARK F. KALINA MARY E. KRASNER I. STEVEN BUTKUS JOHN J. PCOLINSKI, JR. MARK G. PATRICOSKI

100 WEST ROOSEVELT ROAD WHEATON, IL 60187 TELEPHONE (630) 665-9033 TELECOPIER (630) 690-9652

WRITER'S DIRECT EXTENSION: 17

December 30, 2002

Mr. Richard Bernet **EXELON** Legal Services 10 South Dearborn Street 35th Floor Chicago, IL 60603 VIA FACSIMILE 312-394-3950 and Regular Mail

Re:

Jays Foods vs. Commonwealth Edison

Illinois Commerce Commission Complaint 2002-328175

Dear Mr. Bernet:

In response to your letter of today, I enclose a copy of our Engineer's response to the same. This should resolve the questions you have regarding the replacement of the miniature pilot light transformers. We previously provided pictures of the mini-transformers so that you could see (from a non-technical standpoint) that these have no significance to what we are dealing with here. These mini-transformers simply reduce the power to the pilot lights. When the lights were out, it was determined that the transformers were bad / non-operative and were replaced. This has no connection to the over-billing by ComEd. I will talk to you regarding conclusion to this claim on Thursday the 2nd.

Very Truly Yours,

GUERARD, KALINA & BUTKUS

Mark G. Patricoski

MGP/imd Encls.

MARS

LaSalle Associates, Inc.

www.lasallecogen.com

P.O. Box 2878, Gien Ellyn, IL 60138 (630) 858-8110, Fax (630) 469-8688, lasallecogen@aol.com

December 30, 2002

Mr. Mark Patricoski Guerard, Kalina and Butkus 100 W. Roosevelt Rd. Suite A-1 Wheaton, IL 60187

RE: Jays Foods LLC v. ComEd, ICC Complaint No. 2002-328175

Dear Mark:

In response to Mr. Bernet's most recent letter, the pilot light transformers were replaced because they were faulty. When a potential phase to ground was being checked (one or more pilot lights not illuminated) two pilot lights were observed not lit. The cause was not a phase ground, or faulty light bulbs, but faulty (open circuit) pilot light transformers. The transformers were replaced and the pilot lights illuminated confirming a normal condition (no phase to ground).

The only other electrical work performed at Jays in the last sixty days is the change-out of the faulty meter by ComEd.

On a side note, the demand charge billed to Jays is based on a kW reading on the meter that lasts at least 30 minutes and is averaged from three different readings taken on different days of a billing period. A fault occurs for a very short period of time (seconds) before a fuse blows or a breaker trips. Not only is there no evidence of a fault condition, but even if there were, it would have NO impact on the over-billing error.

Very truly yours,

David Patricoski, President LaSalle Associates, Inc.

Exelon.

Business Services Company

Legal Services Business Services Company 10 South Dearborn Street, 35th Floor Chicago, IL 60603 Telephone 312-394-5400 Fax 312-394-3950 www.exeloncorp.com

Mail To: P.O. Box 805379 Chicago, IL 60680-5379

Writer's Direct Contact Information

Direct Dial: (312) 394-3623 Facsimile: (312) 394-3950

E-mail: richard.bernet@exeloncorp.com

December 30, 2002

Via Facsimile 630-690-9652

Mark Patricoski
Guerard, Kalina and Butkus
100 W. Roosevelt Rd.
Suite A-1
Wheaton, IL 60187

RE: Jay Foods LLC v. Commonwealth Edison Company ICC Informal Complaint No. 2002-328175

Dear Mr. Patricoski:

I am in receipt of your December 26th e-mail and December 27th letter with attached letter from LaSalle Associates. I plan to review this additional information with Commonwealth Edison technical personnel; however, in light of the holidays, they will not be available to discuss this matter with me until late this week or early next week. Your correspondence does not fully respond to my December 19th letter as to why the equipment was replaced or whether any other work had been performed on Jays' electrical system in the last 60 days. I await your response. I take your response to mean that you have now provided me with all data that supports Jays' claim.

Finally, your client's complaint has been pending for only a short time and Commonwealth Edison is proceeding with its investigation as to the cause of the increased demand with appropriate dispatch. We are confident that the Illinois Commerce Commission or a court would not find otherwise.

Sincerely.

Richard G. Bernet

Assistant General Counsel, Regulatory

Mark G. Patricoski

From:

"Mark G. Patricoski" <mpatricoski@ameritech.net>

To:

<ri>chard.bernet@exeloncorp.com>

Cc:

<DTPat@aol.com>; <LaSalleCogen@aol.com>

Sent:

Thursday, December 26, 2002 10:54 AM

Attach:

Mark1.doc

Subject:

Jays Foods V. ComEd (ICC 2002-328175)

December 26, 2002

Mr. Richard Bernet Exelon - Legal Dept. (Via E-Mail, Fax and Regular Mail)

Re: Jays Foods 2002-328175

Dear Mr. Bernet:

Attached to this e-mail is a response from the engineering firm of LaSalle Associates and Jays Foods regarding your 12/19/02 letter. Please review and contact the undersigned as quickly as possible to resolve this matter. If a meeting of the experts (engineers) on each side would be helpful in resolving this matter, we would be happy to arrange for the same. I look forward to hearing from you.

Mark G. Patricoski, Attorney 630-665-9033 x 17.

---- Original Message -----

From: <<u>LaSalleCogen@aol.com</u>>

To: <<u>rlowrance@jaysfoods.com</u>>; <<u>mpatricoski@Ameritech.Net</u>>

Sent: Monday, December 23, 2002 1:35 PM

Subject: (no subject)

> Mark,

>

> Please find attached a letter I assembled in regard to the "transformer"

> issue at Jays. Rex supplied me with good information which I used in the

```
> letter. You may want to use this letter to respond to ComEd. Let me know if
> you want me to modify it in any way.
> Very truly yours,
> David Patricoski
> President
> LaSalle Associates, Inc.
> P.O. Box 2878
> Glen Ellyn, IL 60138
> 630-858-8110
> fax-469-8688
> email: LaSalleCogen@aol.com
> www.lasallecogen.com
```

Mark G. Patricoski

From:

<LaSalleCogen@aoi.com>

To:

<rlowrance@jaysfoods.com>; <mpatricoski@Ameritech.Net>

Sent:

Monday, December 23, 2002 1:35 PM

Attach:

Mark1.doc

Subject:

(no subject)

Mark,

Please find attached a letter I assembled in regard to the "transformer" issue at Jays. Rex supplied me with good information which I used in the letter. You may want to use this letter to respond to ComEd. Let me know if you want me to modify it in any way.

Very truly yours,

David Patricoski
President
LaSalle Associates, Inc.
P.O. Box 2878
Glen Ellyn, IL 60138
630-858-8110
fax-469-8688
email: LaSalleCogen@aol.com
www.lasallecogen.com

```
> letter. You may want to use this letter to respond to ComEd. Let me know if
> you want me to modify it in any way.
> Very truly yours,
> David Patricoski
> President
> LaSalle Associates, Inc.
> P.O. Box 2878
> Glen Ellyn, IL 60138
> 630-858-8110
> fax-469-8688
> email: LaSalleCogen@aol.com
> www.lasallecogen.com
```

LaSalle Associates, Inc. www.lasallecogen.com

P.O. Box 2878, Glen Ellyn, IL 60138 (630) 858-8110, Fax (630) 469-8688, lasallecogen@aol.com


December 23, 2002


Mr. Mark Patricoski Guerard, Kalina and Butkus 100 W. Roosevelt Rd. Suite A-1 Wheaton, IL 60187

RE: Jays Foods LLC v. ComEd, ICC Complaint No. 2002-328175

Dear Mark:

I have reviewed the ComEd letter dated 12/19/02 from Richard Bernet. The transformers that he is inquiring about are NOT the types of transformers I believe he thinks the are. They are actually pilot lights that have a mini transformer on them allowing a 6.3 v lamp to operate in a 480 V cabinet. They have absolutely nothing to do with the over billing issue in contention and have no effect on the meter or demand. Please find below photos sent by Rex Lowrance as well as his description of the lights.





E-mail from Rex Lowrance 12/23/02

David,

I was afraid the word "Transformer" was the wrong word to use with them, I should have just said pilot light because that is all it really is. It is the part of the pilot light that allows the use of a 6.3 volt bulb on a 480 volt circuit. Anyway, the information is:

Manufacturer-"idec" Part Number - TWD-0486 We ordered from Steiner Electric

I have enclosed a picture of the back with part number and a side view so anyone can see it is a part of the pilot light. When I measured the voltage on the back of the unit prior to changing out the two transformers, the voltage read 279V & 285V between the read wire and the green wire, so the transformers were open, not shorted.

Rex

I hope this information will help ComEd move along in this process and refund the appropriate funds to Jays Foods.

Very truly yours,

David Patricoski, President

LaSalle Associates, Inc.

Exelon.

Business Services Company

Legal Services Business Services Company 10 South Dearborn Street, 35th Floor Chicago, IL 60603

Telephone 312-394-5400 Fax 312-394-3950 www.exeloncorp.com

Mail To: P.O. Box 805379 Chicago, IL 60680-5379

Writer's Direct Contact Information

Direct Dial: (312) 394-3623 Facsimile: (312) 394-3950

E-mail: richard.bernet@exeloncorp.com

December 19, 2002

Via Facsimile 630-690-9652

Mark Patricoski Guerard, Kalina and Butkus 100 W. Roosevelt Rd. Suite A-1 Wheaton, IL 60187

RE: Jay Foods LLC v. Commonwealth Edison Company ICC Informal Complaint No. 2002-328175

Dear Mr. Patricoski:

I am in receipt of your December 19th letter. ComEd personnel visited Jays' facility yesterday. We understand that two transformers were replaced by Jays in early December. In connection with our evaluation of the claim, it is important for us to know why the transformers were replaced. We would also appreciate the opportunity to inspect the old transformers. Please advise if Jays has performed any other work on its electrical system in the last 60 days. Finally, please provide any other data that supports this claim.

Sincerely,

Richard G. Bernet

Assistant General Counsel, Regulatory

12-19-02; 3:53PM;

Fax



;3:23943950

Date:

December 19, 2002

To:

Mark Patricoski

Fax:

630-690-9652

Transmittal Sheet Plus 1 Page

From:

Richard Bernet

Location:

Legal Services, 35th Floor

10 South Dearborn Street

P.O. Box 805379

Chicago, IL 60680-5379 35 SW CHQ - Legal

Telephone: (312) 394-3623

Fax No:

(312) 394-3950

Email:

richard.bernet@exeloncorp.com

MESSAGE:

Please see attached letter re: Jays Foods.